

April 11, 2011

Hirose Electric Co., Ltd.

Tatsuro Nakamura, President

Hiroshi Fukumoto, Deputy General Manager – Administration

Effects of the April 7, 2011 (Thur.) Late-night “Miyagi Earthquake” (2nd Report)

This report contains information on the effects that the “Miyagi earthquake” which occurred on at 11:32 local time, April 7, 2011 has had on our group of companies. This report is accurate as of 10:00, April 11, 2011, and details are as outlined below.

Details

1. Employee Safety:

We have confirmed that all Hirose company/group employees are safe.

2. Effects of Manufacturing Activities

(1) Group Manufacturing Subsidiaries

(1) Tohoku Hirose Electric Co., Ltd. (Miyako, Iwate Prefecture, Japan)

Manufactured Products: Multi-contact connectors

Damage Status: No damage to buildings or manufacturing equipment.

Manufacturing Status: Electricity that was disrupted during the April 7 aftershock was restored on April 8. Operations returned to normal on April 9.

(2) Koriyama Hirose Electric Co., Ltd. (Koriyama, Fukushima Prefecture, Japan)

Manufactured Products: Multi-contact connectors

Damage Status: No damage to buildings or manufacturing equipment.

Manufacturing Status: Operating as normal.

(3) Ichinoseki Hirose Electric Co., Ltd. (Ichinoseki, Iwate Prefecture, Japan)

Manufactured Products: Multi-contact connectors, Coaxial connectors and other products.

Damage Status: Some damage to buildings and manufacturing equipment. Work is currently underway to repair damage.

Manufacturing Status: Electricity that was disrupted during the April 7 aftershock was restored on April 9. Operations returned to normal on April 10.

(2) Affiliated Companies

Some affiliated companies or sub-contractors were affected by the power blackout, however electricity was restored yesterday (April 10) and they are now operating normally.